To: Matt Francis[m.francis@erllc.com]

From: Way, Steven

Sent: Mon 8/4/2014 10:01:02 PM

Subject: RE: Gold King changes - Deere and Ault

Good plan!

Steven Way
Federal On-Scene Coordinator
Emergency Response Unit
US EPA - Region 8
1595 Wynkoop Street
Denver, CO 80202

Office: 303-312-6723

----Original Message----

From: Matt Francis [mailto:m.francis@erllc.com]

Sent: Monday, August 04, 2014 3:53 PM

To: Way, Steven

Subject: RE: Gold King changes - Deere and Ault

I did. I told him to cap off what we agreed on one invoice and put the additional on another. If we can fit all on the preplanning I will. If not I'll move the new charges to the real TO.

----Original Message-----

From: Way, Steven [mailto:way.steven@epa.gov]

Sent: Monday, August 04, 2014 3:47 PM

To: Matt Francis

Subject: RE: Gold King changes - Deere and Ault

Matt,

I assume that you answered Christoph on funding the corrections.

Steve

Steven Way
Federal On-Scene Coordinator
Emergency Response Unit
US EPA - Region 8
1595 Wynkoop Street
Denver, CO 80202

Office: 303-312-6723

----Original Message-----

From: Christoph Goss [mailto:christoph.goss@deereault.com]

Sent: Thursday, July 31, 2014 3:32 PM

To: Matt Francis Cc: Way, Steven

Subject: RE: Gold King changes

Hi Matt

Thanks for the update. Here are my thoughts:

- 1. Wow, that is a totally different shape and will definitely change the capacity (in a good way). I will get with our drafter tomorrow, revise the sections and send them to our structural engineer.
- 2. I will ask our structural engineer to put one together
- 3. Footer size would stay the same, so volume would depend on number of sets constructed. We will see what spacing the new calculations would allow.

How many sets are there and are we assuming 50' to the brow?

This work will put us over budget. Please confirm that we can proceed at our existing rates.

Christoph

----Original Message-----

From: Matt Francis [mailto:m.francis@erllc.com]

Sent: Thursday, July 31, 2014 3:14 PM

To: Christoph Goss Cc: Way, Steven

Subject: Gold King changes

At the site visit today a couple of things came up for you to adress.

- 1) we put a couple of arch set sections together and measured actual dimensions. The have a diameter of 11'3", are 10' high and 9' wide at the bottom. All measurements are inside. This probably changes your design limitations, so please revise.
- 2) bidders requested a bolt spec
- 3) bidders requested a volume for concrete used in footers (and maybe this changes due to #1?)

We requested they submit follow up questions as soon as possible. I'll fwd them to you as they artive.

Thanks Matt

Sent via the Samsung Galaxy Note® 3, an AT&T 4G LTE smartphone

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. The sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you